CEDAR

For managing various manual torque drivers and wrenches

WDISR-IP series

Manual torque tool management / built-in battery type

The "DIS series" has become easier to use and has higher performance.

It works with a personal computer or PLC to manage torque measurement more highly. For managing manual torque drivers and wrenches.

Color display that can display various information.
Data output is standard equipment for both USB and RS232C.
A series of diverse lineups from up to 500mN･m (0.5N･m) to 1500N･m.
Numerical values such as pass / fail conditions can be set up to 10 channels.
Pass / fail judgment is clearly displayed in color.
Built-in battery drive.

CEDAR

●Color display that can display various information.

●Data output is standard equipment for both USB and RS232C.

●Setting various measurement parameters

Measurement example

Manual torque driver management

Manual torque wrench management

Click operation of torque wrench
Measurement is PD (peak down mode)
For tool check at the start of work

Operation of a torque wrench

The actual torque applied is measured
PP (peak mode)
For worker experience training and tightening operation check

Works with "PC" and "PLC"

Various commands can be input from PLC or personal computer. Finer torque management is possible with external control.

Command list

Clear signal: Clears the display and outputs the held numerical value as data and saves it in memory.

Measurement mode: Change the measurement mode.

Measurement channel: Change individual channels for which conditions such as pass / fail judgment are set.

Peak hold upper limit : Change the pass / fail judgment upper limit of the current channel.

Peak hold lower limit: Change the pass / fail judgment lower limit of the current channel.

Peak down lower limit: Change the peak down judgment start lower limit of the current channel.

Real-time output lower limit: Changed the output lower limit of real-time output.

Auto clear time: Changed the time to automatically clear after the measurement is completed.

**Buzzer notification:** Changed the buzzer notification method.

CEDAR

Specification

Model	WDISR-IP05	WDISR-IP5	WDISR-IP50	WDISR-IP200	WDISR-IP500	WDISR-IP1500
Applications	It is a torque measuring equipment to measure the tightening torque of tightening tools (torque screwdriver, torque wrench, etc.) in screw tightening work.					
Power supply	Internal battery (12 hours continuous operation time, 3 hours charging time)					
Rate input voltage	12V DC					
Measurement range	2.0 ~ 500.0 [mN-m]	0.020 ~ 5.000 [N-m]	0.20 ~ 50.00 [N-m]	2.0 ~ 200.0 [N-m]	2.0 ~ 500.0 [N-m]	20 ~ 1500 [N-m]
Measurement Unit	kgf-cm lbf-in mN-m cN-m	kgf-cm lbf-in N-m cN-m		kgf-cm lbf-in N-m		kgf-m lbf-ft N-m
Accuracy	±0.5% (If 499 digit or less, ±3 digit.) *Maintain a constant temperature during measurement.					
Sampling rate	1000 data / 1sec					

Measurement mode				
	Measurement mode		Data output	Contents
	Peak hold	PP	○	Measure the peak torque.
	Peak down	PD	○	Measure the firs peak torque.
	Real time output	C	○	The data output cycle is approximately 180 data / 1 second.
	Track	TR	—	Mainly used for calibration.
	If the measurement mode is TR, the data isn't outputted.			

Data output	Wired (ASCII format)					
Memory size	800 data					
Auto power off	Power off after 10 minutes of non-use					
Accessories, Attachments	Detector (Refer below)					
	Detector cable					
	AC adaptor					
	Rubber foot					
	—					T-knob×2
	Result of calibration, Certification on calibration, Traceability system figure					

Detector

Model	IP05 / 5	IP50	IP200	IP500	IP1500
Shapes					

		IP05 / 5	IP50	IP200	IP500	IP1500
A	Detector shape	Φ40mm	Φ50mm	Φ60mm	Φ80mm	Φ100mm
B	Height	41.2mm	63mm	79mm	98mm	102.5mm
C	Thickness	5mm	10mm	15mm	15.5mm	33mm
D	Flange size	Φ60mm	Φ90mm	Φ108mm	Φ140mm	Φ170mm
E	Hole position	Φ50mm	Φ74mm	Φ90mm	Φ116mm	Φ140mm
F	Hole size	Φ4.2mm (Every 120°)	Φ6.3mm (Every 120°)	Φ8.3mm (Every 120°)	Φ10.5mm (Every 120°)	Φ13mm (Every 60°)
G	Socket	6.35sq	9.5sq	12.7sq	19sq	25.4sq
	Weight	Around 200g	Around 600g	Around 1kg	Around 2.5kg	Around 7.2kg

CEDAR

Ordering number

The order number indicates the model of the indicator followed by the 'model of the detector', 'detector cable length', 'Packing', 'destination' and 'AC adapter plug'.

```
WDISR ― IP05 ― L1 ― C ― O 1
```

Plug	
1	A plug (Japan, Taiwan, USA)
2	A plug (China)
3	C plug
4	F plug
5	G plug

Destination			
J	Japan	O	Outside Japan

Packing		
C	Cardboard	
A	Plastic case	※1

Detector cable length	
L1	1 meter
L2	2 meters
L4	4 meters

Mode of the detector
IP05
IP5
IP50
IP200
IP500
IP1500

model of the indicator

※1 If you select the detection unit IP200, IP500, or IP1500, the attache case (-A) cannot be used.

About the AC adapter

The certification mark differs depending on the specified plug.

Plug	certification
A plug (Japan, Taiwan, USA) A plug (China) C plug	PSE、FCC、CCC、BSMI、CE
F plug G plug	PSE、CE、UKCA、KC

Packing

The specifications of the case are shown below.

Packing	-C	-A
Specifications	Cardboard	PP
Exterior / Interior		

The contents of a catalog may change specification and a design without a preliminary announcement.